



Service Info



Bleeding process of CSC 510 0097 10

Modified hydraulic connection

Manufacturer: Dacia
Nissan
Renault

For current listing refer to parts catalogue

The hydraulic connection of concentric slave cylinder 510 0097 10 has been modified. It now corresponds to the configuration used in current vehicle production. Unlike in the previous design (Photo 2, right), now two clips (Photo 2, left) are provided at the hydraulic connection point. Prior to installing the concentric slave cylinder, take note of the type of connector on the vehicle side, because a specific bleeding procedure must be followed depending on the design.

When installing the new concentric slave cylinder, all connectors must first be pushed in all the way to the stop. In so doing, both clips must be closed.

Bleeding procedure for vehicle-side connector with short flange (Photo 1):

1. Open clip 2
2. Open clip 1
3. Pull the pipe out until it reaches the first stop
4. Close clip 1
5. Close clip 2
6. Pull the pipe out until it reaches the second stop (Photo 3)
7. Connect the bleeding device and switch it on
8. Remove air until liquid discharge is free of bubbles
9. Push the pipe in until it reaches the stop (Photo 4)
10. Switch off the bleeding device and remove it




Photo 1: Vehicle-side connector with short flange



Photo 2: Previous design with one clip (right), new design with two clips (left)




Photo 3: With the connector pulled out and the clips closed, the bleed hole is open




Photo 4: With the connector pushed in and the clips closed, the bleed hole is closed



Bleeding procedure for vehicle-side connector with long flange (Photo 5):

1. Open clip 2
2. Open clip 1
3. Pull the pipe out until it reaches the stop (Photo 6)
4. Connect the bleeding device and switch it on
5. Remove air until liquid discharge is free of bubbles
6. Close clip 1
7. Close clip 2
8. Push the pipe on until it reaches the stop (Photo 7)
9. Switch off the bleeding device and remove it




Photo 5: Vehicle-side connections with long flange




Photo 6: With the connector pulled out and the clips opened, the bleed hole is open




Photo 7: With the connector pushed in and the clips closed, the bleed hole is closed

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
Fax: +44 (0) 1432 375 760
aftermarket.uk@schaeffler.com
www.repxpert.co.uk

