

SERVICE INFO



Note on installing tensioning pulley 531 0317 10 with base plate fixing

Manufacturers: Audi, Seat, Škoda, Volkswagen

Models:

Audi: A2
Seat: Altea, Arosa, Cordoba, Ibiza III, Ibiza IV, Ibiza V, Inca, Leon, Toledo II

Škoda: Fabia, Octavia, Praktik, Roomster

Volkswagen: Bora, Caddy II, Caddy III, Golf IV, Golf V, Golf VI, Golf Plus, Lupo, New Beetle, Polo

Engines: 1.4, 1.6

OE numbers: 036 109 243 AB (replaced)
036 109 243 AD (replaced)
036 109 243 E (replaced)
036 109 243 L (replaced)
036 109 243 R (replaced)
036 109 243 AF (new)

Part no.: 531 0317 10



Image 1: 531 0317 10 — Tensioning pulley with base plate fixing

When installing tensioning pulley 531 0317 10, always ensure that the base plate is positioned correctly. The base plate must be correctly positioned in the designated retainer on the engine block.

If the base plate is fitted incorrectly, this could cause the tensioning pulley to malfunction.

Note:

It is important to ensure that the base plate is positioned correctly for all tensioning pulleys that feature a base plate fixing.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 05.2011

INA 0076

Subject to technical changes

© 2011 Schaeffler Automotive Aftermarket

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

