



Service Info



New tensioner pulley 531 0859 10

Complete coverage for D5204 and D5244 engines

Manufacturer: Volvo

Models: C30, S40, V40, V50, S60, V60, XC60, C70, V70, XC70, S80, XC90

Engines: D5204, D5244

Art-Nr.: 531 0515 10 (replaced)
531 0859 10 (new)
530 0504 10 (Kit, replaced)
530 0582 10 (Kit, new)

OE-Nummern: 30638278 (replaced)
30677134 (replaced)
30731774 (replaced)
31316658 (replaced)
31316999 (replaced)
31339542 (new)
31258305 (Kit, replaced)
31330188 (Kit, replaced)
31359568 (Kit, new)



Image 1: 531 0859 10 – new tensioner pulley

In the specified vehicles, tensioner pulley 531 0515 10 (figure 2) can only be used for a limited range of engine numbers.

For this reason, Schaeffler Automotive Aftermarket has developed the new tensioner pulley 531 0859 10 (figure 1). This component covers all D5204 and D5244 engines over the entire construction period.

In terms of appearance, the two tensioner pulleys differ only in the design of the timing pointer.

Kit 530 0504 10 with tensioner pulley 531 0515 10 is replaced by kit 530 0582 10 with the new tensioner pulley.

Observe the specifications of the vehicle manufacturer!



Image 2: 531 0515 10 – old tensioner pulley

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-info@schaeffler.com
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

