




	MEYLE no.	Referencia no.
Bushing:	100 610 0027/HD	1 K0 407 183 E 6Q0 407 183 A
	left:*	right:*
Mount:	100 610 0014/HD 100 199 0085/HD	100 610 0014/HD 100 199 0086/HD
Control arm:	116 050 0072/HD 116 050 0002/HD 116 050 0032/HD	116 050 0072/HD 116 050 0003/HD 116 050 0033/HD
Repair kit:	100 610 0085/HD	100 610 0086/HD
*reference numbers at www.meyle.com		

Control arm bushing to fit Audi, Seat, Skoda, VW



as OE

Problem

Rubber bearing does not provide enough cornering force and can wear out

Effect

Steering play, accurate lateral guidance no longer possible

Solution




Reinforcement of the critical rubber dimensions for enhanced bonding of the inner control arm mount to the outer sleeve

Advantage

An optimised component with a longer service life

as OE



MEYLE-HD- version

