

# SERVICE INFO



## Visible differences between cam follower 422 0102 10 and support element 420 0222 10

### Vehicle

**manufacturers:** Audi, Seat, Skoda, Volkswagen

### Models:

**Audi:** A3, A4, A5, A6, A8, Q5, Q7, TT

**Seat:** Altea, Exeo, Ibiza V

**Skoda:** Octavia, Superb, Yeti

**VW:** Golf V, Golf VI, Jetta III, Passat, Phaeton, Polo, Scirocco, Tiguan, Touareg, Multivan T5, Transporter T5

### Engines:

1.6 TDI, 2.0 TDI, 2.5 TDI, 2.7 TDI, 3.0 TDI, 4.0 TDI, 4.2 TDI, 6.0 TDI

### OE Nos.:

- (1) 059 109 417 J  
059 109 417 G
- (2) 059 109 521 G  
03L 109 521  
03L 109 521 A

### Part Nos.:

- (1) 422 0076 10  
(replaced)
- (1) 422 0102 10 (new)
- (2) 420 0221 10  
(replaced)
- (2) 420 0222 10 (new)



**Image 1:** Design 1

When replacing the cam follower and hydraulic support element, the versions illustrated in images 1 and 2 may have been used in the vehicle.

Schaeffler Automotive Aftermarket currently supply the version illustrated in image 2 but can be used to replace the version in image 1.



**Image 2:** Design 2

### Note:

#### Always replace in sets!

Always replace the complete set if one or more of the hydraulic valve clearance compensation components is faulty. To avoid multiple repairs and higher costs, the cam follower and support element should always be replaced at the same time.

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

Appropriate spare parts can be found in our on-line catalogue at [www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com) or in RepXpert at [www.RepXpert.com](http://www.RepXpert.com).

Issued 05.2010

**INA 0060**

Subject to technical changes

© 2010 Schaeffler Automotive Aftermarket

### For further information:

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

[www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com)

\* Calls from within the UK 08457 001100

