



Service Info



LuK DMF 415 0388 10

Modified sensor ring

Manufacturer: Ford

Model: Transit

Model year: 2004 -

Engine: 2,4 TDCi

LuK DMF: 415 0388 10



Image 1: Previous sensor ring design



Image 2: New sensor ring design

As part of the on-going development of our products, the sensor ring for engine speed sensing and the bearing arrangement in the dual mass flywheel (DMF) 415 0388 10 has been modified.

The new generation sensor ring differs to its predecessor in that it features a reduced material thickness and a different tooth shape.

Please inspect the sensor ring for transport damage before fitting. Despite their different designs, both versions of the DMF can be used universally in the vehicles specified in the catalogues.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-info@schaeffler.com
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

