

Service Info



Concentric slave cylinders 510 0088 10 and 510 0164 10


Different size hydraulic connections

Manufacturers: Dacia Nissan

LuK part no.:

Renault

o.: 510 0088 10 510 0164 10



For replacement, Schaeffler Automotive Aftermarket recommends two repair variants:

- Concentric slave cylinders with small connections (Fig. 1) were used in the original equipment. Depending on the vehicle assignment, these can be replaced by LuK part no.: 510 0088 10 or 510 0164 10
- A concentric slave cylinder with a large connection (Fig. 2) originates from a previous repair, whereby the hydraulic connection of the vehicle was converted. When installing LuK part no.: 510 0088 10 or 510 0164 10 the vehicle must be converted back to the small connection, i.e. a new hydraulic pipe must be fitted

Fig. 1: Concentric slave cylinders with small hydraulic connections



Fig. 2: Concentric slave cylinder with large hydraulic connection

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264* Fax: +44 (0) 1432 375 760 hfd-info@schaeffler.com www.schaeffler-aftermarket.co.uk * Calls from within the UK 08457 001100



