

## Put an end to leaks: with MEYLE-HD water pumps to beat frustration in the workshop!

**21 new MEYLE water pumps in HD quality for numerous VW and Porsche vehicle applications.**

Problems with leaky water pumps and the resulting engine damage are a source of great annoyance in the everyday life of a garage. After feedback from the market and at the request of garages, we have therefore dedicated ourselves to the subject of water pumps - with the aim of improving the quality and specifically preventing leaks.

After a thorough development phase and successful tests, there are now 21 new water pumps in HD quality available from MEYLE. By combining uniquely tough

components, MEYLE-HD water pumps offer quality standards far higher than what can normally be found on the free market for components:

- Made in Germany
- Extremely hard-wearing mechanical seal in OE quality with SiC/SiC seal faces (silicon carbide) and high resistance to abrasive materials
- Housing seal resistant to high temperatures
- Water pump bearings in OE-equivalent quality
- Four-year guarantee on all MEYLE-HD parts plus 100,000 miles performance guarantee\*



**4-year guarantee plus  
100,000-miles performance  
guarantee for all MEYLE-HD  
water pumps\***



\* For more information on the MEYLE guarantee policy visit [www.meyle.com/guarantee-certificate](http://www.meyle.com/guarantee-certificate)

MEYLE no. [Short no.:]	Vehicle applications
11-13-220 0004/HD [MWP0082HD]	VW diesel engines 1.9-2.0 TDI
113 220 0018/HD [MWP0164HD]	VW diesel engines 2.5 TDI
113 012 0042/HD [MWP0131HD]	VW diesel engines 2.5 TDI
113 220 0005/HD [MWP0152HD]	VW petrol engines 1.6i   1.8i   2.0i
113 012 0033/HD [MWP0123HD]	VW petrol engines 1.8 TSI   2.0 TSI
113 220 0023/HD [MWP0169HD]	VW petrol engines 2.0 TFSI
113 220 0011/HD [MWP0158HD]	VW diesel engines 1.2 , 1.6 und 2.0 TDI
113 220 0021/HD [MWP0167HD]	VW petrol engines 1.8   1.8 GTI   1.8T   2.0
113 012 0027/HD [MWP0120HD]	VW petrol engines 1.4   1.4 16V
113 012 0040/HD [MWP0129HD]	VW diesel engines 1.2 TDI   1.4 TDI   1.9 TDI   2.0 SDI
113 012 0056/HD [MWP0144HD]	VW diesel and petrol engines 2.4   2.7   3.0   3.1   3.2
113 220 0006/HD [MWP0153HD]	Audi petrol engines 2.8   3.2
113 220 0017/HD [MWP0163HD]	Porsche engines 2.5   2.7   3.4   3.6   S 3.2
413 220 0000/HD [MWP0556HD]	Porsche engines 3.0   3.6 Turbo   4.8   4.8 GTS   4.8 Turbo   4.8 Turbo S   GTS 4.8   S 4.8   Turbo S 4.8
413 220 0001/HD [MWP0560HD]	Porsche engines 4.5   Turbo 4.5
413 220 0002/HD [MWP0564HD]	Porsche engines 2.7   3.2   3.4   3.6   3.8
413 220 0003/HD [MWP0561HD]	Porsche engines 2.7   3.2   3.4   3.6   3.8
713 220 0008/HD [MWP0498HD]	Citroën   Fiat   Ford   Mazda   Peugeot   Toyota   Diesel- engines 1.4

### Information

When replacing the water pump, the complete cooling system must always be thoroughly flushed and then refilled with new, specified coolant. Pay attention to the manufacturer's instructions.