

SERVICE-INFO



Replacement note for repair kit with over-running alternator pulley and flexible coupling sleeve

Vehicle manufacturer:	Volkswagen
Models:	Multivan T5, Phaeton, Touareg, Transporter T5
Engines:	2.5 TDI, 5.0 TDI
Engine codes:	AJS, AXE, AXD, AYH, BAC, BLE, BLJ, BLK, BNZ, BPC, BPE, BWF, CBWA
OE-Nos:	(1) 070 903 201 E (over-running alternator pulley) (2) 070 903 327 C / D (flex. coupling sleeve)
Item no. (OLD):	(1) 535 0118 10 (over-running alternator pulley) (2) 536 0310 10 (flex. coupling sleeve) (3) 530 0493 10 (repair kit)
Item no. (NEW):	(1) 535 0118 10 (over-running alternator pulley) (2) 535 0185 10* (flex. coupling sleeve) (3) 535 0186 10 (repair kit)



Figure 1: Over-running alternator pulley with flexible coupling sleeve and spur gear

Schaeffler Automotive Aftermarket has implemented a part number replacement for the parts mentioned above. The replacement parts themselves have not been modified.

Figure 1 illustrates how the individual components are arranged in the spur gear of the Volkswagen engines detailed above.

In this drive, the over-running alternator pulley 535 0118 10 (1) and the coupling sleeve 535 0185 10* (2) are used for both the alternator (ALT) and the air conditioning compressor (AC).

Schaeffler Automotive Aftermarket also offers the repair kit 535 0186 10 (3) as a complete repair solution; the kit includes the over-running alternator pulley and the coupling sleeve.

Key to figure 1:

- (1) Over-running alternator pulley 535 0118 10
- (2) Flex. coupling sleeve 535 0185 10*
- (3) Repair kit 535 0186 10
- (CA) Camshaft gear
- (WP) Water pump gear
- (CS) Crankshaft timing gear
- (OP) Oil pump gear
- (ALT) alternator connection
- (AC) Air conditioning compressor connection



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 01.2010

INA 0051

Technical subject to change

© 2010 Schaeffler Automotive Aftermarket oHG

*) not available separately

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

