



## HD-Stabilizer links



as OE



### Problem

Intense strain causes wear and stress of the components

### Effect

Premature failure of the ball joint  
Noise from the front axle



### Solution



- Enlarged ball diameter (22 mm)
- Reinforced link rod
- MEYLE high-tech grease
- Wear resistant blue plastic seat

### Advantage

Significantly longer service life thanks to reinforced design

as OE



MEYLE-HD-version

